


52-4080B PoE Switch, power wiring

Important:


If a 52-4080B PoE switch is operated in redundancy mode, audible noise can arise due to the connected 52-4048 Desktop Power Supplies, since no load share is effected by these power supplies.

Load share is effected in the Power Supply Frames 52-5081 and 52-5083 in combination with the Power Supply modules 52-5047 or 52-5048. Moreover, apart from using 52-4080B PoE switches, it is possible to install 52-5088 PoE switches in the Power Supply Frames 52-5081 and 52-5083.

redundant wiring - factory default



connect through *



*) wiring equivalent to 52-4080A